



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: Dal-Tile
Project: Waste Water

SDG No.: Q3420
RunNo.: LB137615

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.504	0.5	101	90-110	10/22/2025
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.502	0.5	100	90-110	10/22/2025
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.500	0.5	100	90-110	10/22/2025

Initial and Continuing Calibration Verification

Client: Dal-Tile

SDG No.: Q3420

Project: Waste Water

RunNo.: LB137617

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Ammonia as N	mg/L	0.97	1	97	90-110	10/22/2025
Sample ID: CCV1 Ammonia as N	mg/L	0.97	1	97	90-110	10/22/2025
Sample ID: CCV2 Ammonia as N	mg/L	0.96	1	96	90-110	10/22/2025
Sample ID: CCV3 Ammonia as N	mg/L	0.96	1	96	90-110	10/22/2025
Sample ID: CCV4 Ammonia as N	mg/L	0.96	1	96	90-110	10/22/2025
Sample ID: CCV5 Ammonia as N	mg/L	0.98	1	98	90-110	10/22/2025

Initial and Continuing Calibration Verification

Client: Dal-Tile

SDG No.: Q3420

Project: Waste Water

RunNo.: LB137634

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV1						
Cyanide		mg/L	0.094	0.099	95	85-115	10/24/2025
Sample ID:	CCV1						
Cyanide		mg/L	0.24	0.25	96	90-110	10/24/2025
Sample ID:	CCV2						
Cyanide		mg/L	0.24	0.25	96	90-110	10/24/2025

Initial and Continuing Calibration Verification

Client: Dal-Tile

SDG No.: Q3420

Project: Waste Water

RunNo.: LB137729

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Phosphorus, Total	mg/L	0.517	0.50	103	90-110	10/31/2025
Sample ID: CCV1 Phosphorus, Total	mg/L	0.502	0.50	100	90-110	10/31/2025
Sample ID: CCV2 Phosphorus, Total	mg/L	0.493	0.50	99	90-110	10/31/2025