

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG

Project: Washington St- Bay St OP

Client Sample ID: JB-2 Lab Sample ID: Q3440-04 Date Collected: 10/22/25 22:30

Date Received: 10/23/25 SDG No.: Q3440 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Corrosivity	7.70	Н	1	0	0	pН		10/24/25 13:50	9045D	
Ignitability	NO		1	0	0	oC		10/24/25 10:35	1030	
Reactive Cyanide	0.050	U	1	0.0084	0.050	mg/Kg	10/24/25 12:15	10/24/25 14:44	9012B	
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	10/24/25 11:15	10/24/25 13:43	9034	

Comments: pH result reported at temperature 20.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits