

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client:Tully Environmental, IncDate Collected:10/22/25 11:15Project:Transfer Station-SPDESDate Received:10/23/25Client Sample ID:001 Willets Pt Blvd (Oct)DLSDG No.:Q3441Lab Sample ID:Q3441-01DLMatrix:WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ammonia as N	6.40	D	5	0.15	0.50	mg/L	10/28/25 14:50	10/29/25 12:15	SM 4500-NH3 B plus G-21

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits