

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Weston Solutions, Inc.

Project: RFP 905

Client Sample ID: P001-TW4-251023-01

Lab Sample ID: Q3447-07

Date Collected: 10/23/25 11:30

100

Date Received: 10/23/25

SDG No.: Q3447 Matrix: SOIL

% Solid:

Parameter	Conc.	Qua.	DF M	DL LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.043	J	1 0.	041 0.24	mg/Kg	10/24/25 10:10	10/24/25 12:32	9012B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits