

Report of Analysis

Client: HDR, Inc.
Project: PVWC Linear Construction
Client Sample ID: B8-0.0-1.0-20251023
Lab Sample ID: Q3466-03

Date Collected: 10/23/25 10:30
Date Received: 10/24/25
SDG No.: Q3466
Matrix: SOIL
% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	6.40	H	1	0	0	pH		10/27/25 14:55	9045D
Ignitability	NO		1	0	0	oC		10/27/25 15:22	1030
Reactive Cyanide	0.017	J	1	0.0083	0.049	mg/Kg	10/28/25 08:50	10/28/25 11:24	9012B
Reactive Sulfide	6.31	J	1	0.20	10.0	mg/Kg	10/28/25 09:05	10/28/25 15:28	9034

Comments: pH result reported at temperature 21.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits