

LAB CHRONICLE

OrderID:	Q3466	OrderDate:	10/24/2025 3:18:10 PM
Client:	HDR, Inc.	Project:	PVWC Linear Construction
Contact:	Andrew Wadden	Location:	D41,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3466-02	B8-0.0-1.0-20251023	SOIL			10/23/25 10:30			10/24/25
			Cyanide	9012B		10/28/25	10/28/25 13:30	
			Hexavalent Chromium	7196A		10/27/25	10/27/25 12:39	
			Paint Filter	9095B			11/03/25 14:35	
Q3466-03	B8-0.0-1.0-20251023	SOIL			10/23/25 10:30			10/24/25
			Corrosivity	9045D			10/27/25 14:55	
			Ignitability	1030			10/27/25 15:22	
			Reactive Cyanide	9012B		10/28/25	10/28/25 11:24	
			Reactive Sulfide	9034		10/28/25	10/28/25 15:28	
Q3466-05	B9-0.0-1.0-20251023	SOIL			10/23/25 11:50			10/24/25
			Cyanide	9012B		10/28/25	10/28/25 13:30	
Q3466-07	B7-1.0-2.0-20251023	SOIL			10/23/25 13:50			10/24/25
			Cyanide	9012B		10/28/25	10/28/25 13:37	