

## LAB CHRONICLE

|                 |               |                   |                          |
|-----------------|---------------|-------------------|--------------------------|
| <b>OrderID:</b> | Q3466         | <b>OrderDate:</b> | 10/24/2025 3:18:10 PM    |
| <b>Client:</b>  | HDR, Inc.     | <b>Project:</b>   | PVWC Linear Construction |
| <b>Contact:</b> | Andrew Wadden | <b>Location:</b>  | D41,VOA Ref. #2 Soil     |

| LabID    | ClientID            | Matrix | Test          | Method | Sample Date | Prep Date | Anal Date | Received |
|----------|---------------------|--------|---------------|--------|-------------|-----------|-----------|----------|
| Q3466-02 | B8-0.0-1.0-20251023 | SOIL   | PCB           | 8082A  | 10/23/25    | 10/28/25  | 10/28/25  | 10/24/25 |
|          |                     |        | Pesticide-TCL | 8081B  |             | 10/28/25  | 10/28/25  |          |
| Q3466-05 | B9-0.0-1.0-20251023 | SOIL   | PCB           | 8082A  | 10/23/25    | 10/28/25  | 10/28/25  | 10/24/25 |
|          |                     |        | Pesticide-TCL | 8081B  |             | 10/28/25  | 10/28/25  |          |
| Q3466-07 | B7-1.0-2.0-20251023 | SOIL   | PCB           | 8082A  | 10/23/25    | 10/28/25  | 10/28/25  | 10/24/25 |
|          |                     |        | Pesticide-TCL | 8081B  |             | 10/28/25  | 10/28/25  |          |