

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Alliance Technical Group, LLC - Newark

Project: NJ Soil PT

Client Sample ID: HW1025-PT-SOL-SOIL

Lab Sample ID: Q3483-24

Date Collected: 10/27/25 10:00

Date Received: 10/29/25 SDG No.: Q3483

Matrix: SOIL % Solid: 75.5

Parameter	Conc. Qu	ua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TS	75.5	1 1.00	5.00	%		10/30/25 13:0	00 SM 2540 B-20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits