

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: PSEG Date Collected: 10/29/25 11:58

Project: Lawrenceville HQ Date Received: 10/29/25 Client Sample ID: LAW-25-0151 SDG No.: Q3490 Lab Sample ID: Q3490-02 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Corrosivity	7.06	Н	1	0	0	рН		10/30/25 12:18	9045D	
Ignitability	NO		1	0	0	oC		10/31/25 11:15	1030	
Reactive Cyanide	0.011	J	1	0.0083	0.049	mg/Kg	10/30/25 10:15	10/30/25 13:25		
Reactive Sulfide	4.79	J	1	0.20	10.0	mg/Kg	10/30/25 09:15	10/30/25 13:36	9034	

Comments: pH result reported at temperature 21.9 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits