

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 10/31/25 11:30

Project: Summit Gas and Appliance Service (SU)

Client Sample ID: SU-04-103125

Lab Sample ID: Q3515-01

Matrix: SOIL

% Solid: 84.5

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.14	J	1	0.049	0.29	mg/Kg	11/03/25 10:10	11/03/25 15:18	9012B
Hexavalent Chromium	0.082	U	1	0.082	0.47	mg/Kg	11/03/25 09:20	11/03/25 13:13	7196A
Paint Filter	1.00	IJ	1	1.00	1 00	m1/100gm		11/03/25 14:42	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits