

## Report of Analysis

Client: Remington & Vernick Engineers  
Project: Edison Landfill  
Client Sample ID: MW-6DL  
Lab Sample ID: Q3534-01DL

Date Collected: 11/03/25 10:45  
Date Received: 11/04/25  
SDG No.: Q3534  
Matrix: WATER  
% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TKN	58.9	D	10	1.10	5.00	mg/L	11/06/25 09:10	11/06/25 16:25	SM4500-N Org C-21 plus NH3 B plus G-21

Comments: \_\_\_\_\_

U = Not Detected  
LOQ = Limit of Quantitation  
MDL = Method Detection Limit  
LOD = Limit of Detection  
D = Dilution  
Q = indicates LCS control criteria did not meet requirements  
H = Sample Analysis Out Of Hold Time

J = Estimated Value  
B = Analyte Found in Associated Method Blank  
\* = indicates the duplicate analysis is not within control limits.  
E = Indicates the reported value is estimated because of the presence of interference.  
OR = Over Range  
N = Spiked sample recovery not within control limits