

Report of Analysis

Client: Remington & Vernick Engineers
Project: Edison Landfill
Client Sample ID: MW-EB-1
Lab Sample ID: Q3534-05

Date Collected: 11/03/25 15:00
Date Received: 11/04/25
SDG No.: Q3534
Matrix: WATER
% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Nitrite	0.074	U	1	0.074	0.60	mg/L		11/04/25 19:29	300.0
Nitrate	0.095	U	1	0.095	0.50	mg/L		11/04/25 19:29	300.0
Nitrate+Nitrite	0.17	U	1	0.17	1.10	mg/L		11/04/25 19:29	300.0
BOD5	116		1	0.20	2.00	mg/L		11/05/25 10:10	SM 5210 B-16
COD	140		1	1.50	10.0	mg/L		11/07/25 13:10	SM 5220 D-11
Cyanide	0.061	J	1	0.048	0.25	mg/L	11/07/25 10:15	11/07/25 15:48	9012B
Dissolved Hexavalent Chromium	0.0030	U	1	0.0030	0.010	mg/L		11/04/25 16:50	7196A
Oil and Grease	5.40		1	0.29	5.00	mg/L		11/07/25 10:30	1664A
pH	6.32	H	1	0	0	pH		11/05/25 10:40	9040C
TDS	920		1	1.00	10.0	mg/L		11/05/25 11:30	SM 2540 C-20
TKN	30.1	OR	1	0.11	0.50	mg/L	11/06/25 09:10	11/06/25 15:42	SM4500-N Org C-21 plus NH3 B plus G-21

Comments: pH result reported at temperature 20.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits