

Report of Analysis

Client: Remington & Vernick Engineers
Project: Edison Landfill
Client Sample ID: MW-9
Lab Sample ID: Q3552-03

Date Collected: 11/04/25 16:00
Date Received: 11/05/25
SDG No.: Q3552
Matrix: WATER
% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Nitrite	0.18	J	1	0.074	0.60	mg/L		11/05/25 16:30	300.0
Nitrate	3.90		1	0.095	0.50	mg/L		11/05/25 16:30	300.0
Nitrate+Nitrite	4.08		1	0.17	1.10	mg/L		11/05/25 16:30	300.0
BOD5	397		1	0.20	2.00	mg/L		11/06/25 13:00	SM 5210 B-16
COD	215	D	5	7.50	50.0	mg/L		11/14/25 14:04	SM 5220 D-11
Cyanide	0.80		1	0.047	0.25	mg/L	11/07/25 10:15	11/07/25 15:56	9012B
Dissolved Hexavalent Chromium	0.0030	U	1	0.0030	0.010	mg/L		11/05/25 17:09	7196A
Oil and Grease	1.10	J	1	0.29	5.00	mg/L		11/07/25 10:30	1664A
pH	6.87	H	1	0	0	pH		11/06/25 08:50	9040C
TDS	870		1	1.00	10.0	mg/L		11/06/25 11:30	SM 2540 C-20
TKN	33.6	OR	1	0.11	0.50	mg/L	11/11/25 08:10	11/12/25 11:43	SM4500-N Org C-21 plus NH3 B plus G-21

Comments: pH result reported at temperature 20.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits