

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Lockwood, Kessler & Bartlett, Inc.

Project:Syosset Landfill 2025Date Received:11/06/25Client Sample ID:SY-10DDLSDG No.:Q3560Lab Sample ID:Q3560-01DLMatrix:WATER

% Solid: 0

Date Collected: 11/05/25 09:15

		_								
Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Ammonia as N	7.40	D	10	0.30	1.00	mg/L	11/10/25 11:40	11/11/25 13:06	SM 4500-NH3 B plus G-21	
Chloride	503	D	200	38.0	120	mg/L		11/07/25 11:31		

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits