

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 11/06/25 11:15

Project: Oradell Gas and Appliance Service (OR) Date Received: 11/06/25 Client Sample ID: OR-03-11062025 SDG No.: Q3564 Lab Sample ID: Matrix: SOIL Q3564-01

% Solid: 93.8

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.044	U	1	0.044	0.26	mg/Kg	11/07/25 08:10	11/07/25 16:34	9012B
Hexavalent Chromium	0.073	U	1	0.073	0.42	mg/Kg	11/10/25 09:10	11/10/25 12:40	7196A
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		11/10/25 10:25	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits