

## Report of Analysis

Client: Remington & Vernick Engineers  
Project: Edison Landfill  
Client Sample ID: MW-2DL  
Lab Sample ID: Q3569-01DL

Date Collected: 11/05/25 12:00  
Date Received: 11/06/25  
SDG No.: Q3569  
Matrix: WATER  
% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Nitrate	13.2	D	5	0.48	2.50	mg/L		11/07/25 11:09	300.0
TKN	35.9	D	10	1.10	5.00	mg/L	11/11/25 08:10	11/12/25 12:26	SM4500-N Org C-21 plus NH3 B plus G-21

Comments: \_\_\_\_\_

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits