

Duplicate Sample Summary

Client: Tully Environmental, Inc Project: Transfer Station-SPDES Client ID: SY-10DDUP	SDG No.: Q3575 Sample ID: Q3560-01 Percent Solids for Spike Sample: 0
--	--

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Ammonia as N	mg/L	+/-20	8.10	OR	8.10	OR	1	0		11/11/2025
Ammonia as N	mg/L	+/-20	7.40	D	7.40	D	10	0		11/11/2025

Duplicate Sample Summary

Client: Tully Environmental, Inc	SDG No.: Q3575
Project: Transfer Station-SPDES	Sample ID: Q3560-01
Client ID: SY-10DMSD	Percent Solids for Spike Sample: 0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Ammonia as N	mg/L	+/-20	9.10	OR	9.10	OR	1	0		11/11/2025

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	Q3575
Project:	Transfer Station-SPDES	Sample ID:	Q3578-01
Client ID:	MH-1172025DUP	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
BOD5	mg/L	+/-20	469		466		1	0.64		11/07/2025

Duplicate Sample Summary

Client: Tully Environmental, Inc	SDG No.: Q3575
Project: Transfer Station-SPDES	Sample ID: Q3578-01
Client ID: MH-1172025MSD	Percent Solids for Spike Sample: 0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Oil and Grease	mg/L	+/-18	115		113		1	1.23		11/13/2025