

Initial and Continuing Calibration Verification

Client: Remington & Vernick Engineers

SDG No.: Q3586

Project: Edison Landfill

RunNo.: LB137839

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.489	0.5	98	90-110	11/10/2025
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.495	0.5	99	90-110	11/10/2025
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.491	0.5	98	90-110	11/10/2025
Sample ID: CCV3 Hexavalent Chromium	mg/L	0.489	0.5	98	90-110	11/10/2025
Sample ID: CCV4 Hexavalent Chromium	mg/L	0.493	0.5	99	90-110	11/10/2025

Initial and Continuing Calibration Verification

Client: Remington & Vernick Engineers

SDG No.: Q3586

Project: Edison Landfill

RunNo.: LB137840

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Cyanide	mg/L	0.096	0.099	97	90-110	11/10/2025
Sample ID: CCV1 Cyanide	mg/L	0.24	0.25	96	90-110	11/10/2025
Sample ID: CCV2 Cyanide	mg/L	0.24	0.25	96	90-110	11/10/2025
Sample ID: CCV3 Cyanide	mg/L	0.24	0.25	96	90-110	11/10/2025
Sample ID: CCV4 Cyanide	mg/L	0.25	0.25	100	90-110	11/10/2025