

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 11/07/25 15:55

Project: Trenton Gas and Appliance Service (TR)

Client Sample ID: TR-06-11072025

Lab Sample ID: Q3588-01

Matrix: SOIL

% Solid: 93.9

LOQ / CRQL Units Parameter Conc. Qua. DF MDL **Prep Date** Date Ana. Ana Met. 0.043 0.043 Cyanide U 1 0.26 mg/Kg 11/10/25 08:15 11/10/25 14:47 9012B Hexavalent Chromium 0.069 U 1 0.069 0.39 mg/Kg 11/10/25 09:10 11/10/25 12:48 7196A Paint Filter 1.00 U 1 1.00 1.00 ml/100gm 11/11/25 14:35 9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits