

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 11/07/25 16:20

Project: Trenton Gas and Appliance Service (TR) Date Received: 11/07/25 Client Sample ID: TR-01-11072025 SDG No.: Q3588 Lab Sample ID: Matrix: SOIL Q3588-03

% Solid: 92.6

| Parameter | Conc. | Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. | |
|---------------------|-------|------|----|-------|------------|----------|----------------|----------------|----------|--|
| Cyanide | 0.057 | J | 1 | 0.044 | 0.26 | mg/Kg | 11/10/25 08:15 | 11/10/25 14:47 | 9012B | |
| Hexavalent Chromium | 0.069 | U | 1 | 0.069 | 0.39 | mg/Kg | 11/10/25 09:10 | 11/10/25 12:49 | 7196A | |
| Paint Filter | 1.00 | U | 1 | 1.00 | 1.00 | ml/100gm | | 11/11/25 14:42 | 9095B | |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits