

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 11/10/25 10:41

Project: PSEG Orange Gas Date Received: 11/10/25
Client Sample ID: EO-CONCRETE SDG No.: Q3598
Lab Sample ID: Q3598-02 Matrix: SOIL
% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	11.3	Н	1	0	0	рН		11/10/25 16:37	9045D
Ignitability	NO		1	0	0	oC		11/11/25 11:18	1030
Reactive Cyanide	0.050	U	1	0.0083	0.050	mg/Kg	11/12/25 11:00	11/12/25 16:07	9012B
Reactive Sulfide	1.58	J	1	0.20	10.0	mg/Kg	11/12/25 08:30	11/12/25 12:52	9034

Comments: pH result reported at temperature 23.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits