

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Roman E&G Corp Date Collected: 11/10/25 14:45
Project: MCUA - New Brunswick Date Received: 11/10/25

Project: MCUA - New Brunswick Date Received: 11/10/25
Client Sample ID: S-2 SDG No.: Q3604
Lab Sample ID: Q3604-02 Matrix: SOIL
% Solid: 82.7

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.66	Н	1	0	0	рН		11/12/25 14:37	9045D
Ignitability	NO		1	0	0	oC		11/11/25 13:03	1030
Reactive Cyanide	0.0084	U	1	0.0084	0.050	mg/Kg	11/12/25 11:00	11/12/25 16:22	9012B
Reactive Sulfide	3 16	Ī	1	0.20	10.0	mσ/K σ	11/11/25 16:05	11/12/25 09:42	9034

Comments: pH result reported at temperature 20.1 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits