

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Total Quality Environmental Inc. Date Collected: 11/11/25 Project: Total Quality Environmental Inc Date Received: 11/11/25 Client Sample ID: 1st Fl drinking fountain 1st drow SDG No.: Q3607 Lab Sample ID: Q3607-03 Matrix: Water Level (low/med): % Solid: 0 low

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	2.27	J 1 1.15	6.00	ug/L	11/12/25 11:02	11/12/25 21:15	6010D	M3010A

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits