

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Dal-Tile Date Collected: 11/11/25 13:20
Project: Waste Water - Dickson Plant Date Received: 11/12/25

Client Sample ID: CYANIDEDL SDG No.: Q3616
Lab Sample ID: Q3616-04DL Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.65	D	2	0.0024	0.010	mg/L	11/14/25 08:10	11/14/25 14:21	SM 4500-CN C-21 plus E-21

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits