

Report of Analysis

Client: ENTACT
Project: Whittaker Coatings Site – E9125B
Client Sample ID: EME-TOP-SOIL
Lab Sample ID: Q3618-01

Date Collected: 11/12/25 10:00
Date Received: 11/12/25
SDG No.: Q3618
Matrix: SOIL
% Solid: 70.3

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.73		1	0.057	0.34	mg/Kg	11/14/25 08:10	11/14/25 12:19	9012B
Hexavalent Chromium	0.11	J	1	0.099	0.57	mg/Kg	11/13/25 12:00	11/13/25 15:43	7196A
pH	6.53	H	1	0	0	pH		11/13/25 08:35	9045D
TOC	22700	OR	1	28.9	250	mg/Kg		11/18/25 11:35	9060A
Trivalent Chromium	14.1		1	0.71	0.71	mg/Kg		11/13/25 15:43	6010D

Comments: pH result reported at temperature 21.4 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits