

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Ambric Technology Corporation Date Collected: 11/12/25 Project: 6506 Haverford Road Date Received: 11/12/25 Client Sample ID: GP-B3(13.2) SDG No.: Q3619 Lab Sample ID: Q3619-14 Matrix: SOIL Level (low/med): % Solid: 91 low

Cas	Parameter	Conc.	Qua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	7.38	1 0.13	0.58	mg/Kg	11/13/25 10:55	11/13/25 16:12	6010D	SW3050

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits