

Report of Analysis

Client: Parkway Generation Operating LLC
Project: Linden Generating Station - Towers
Client Sample ID: TOWER-1
Lab Sample ID: Q3629-01

Date Collected: 11/13/25 10:30
Date Received: 11/13/25
SDG No.: Q3629
Matrix: WATER
% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TDS	3260		1	1.00	10.0	mg/L		11/13/25 16:30	SM 2540 C-20
TSS	10.5		1	1.00	4.00	mg/L		11/17/25 12:30	SM 2540 D-20

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits