

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client:Dal Tile - Quartz PlantDate Collected:11/07/25 10:42Project:Quartz Plant - Stormwater Bench MonitoringDate Received:11/14/25Client Sample ID:OUTFALL-001SDG No.:Q3644

Lab Sample ID: Q3644-01 Matrix: WATER % Solid: 0

| Parameter | Conc. Qua. | DF MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|------------|--------|------------|-------|-----------|----------------|--------------|
| TSS | 11.4 | 1 1.00 | 4.00 | mg/L | | 11/14/25 14:00 | SM 2540 D-20 |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits