

Report of Analysis

| | | | |
|-------------------|--|-----------------|----------------|
| Client: | Dal Tile - Quartz Plant | Date Collected: | 11/07/25 11:05 |
| Project: | Quartz Plant - Stormwater Bench Monitoring | Date Received: | 11/14/25 |
| Client Sample ID: | OUTFALL-004 | SDG No.: | Q3644 |
| Lab Sample ID: | Q3644-04 | Matrix: | WATER |
| | | % Solid: | 0 |

| Parameter | Conc. | Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|-------|------|----|------|------------|-------|-----------|----------------|--------------|
| TSS | 25.4 | | 1 | 1.00 | 4.00 | mg/L | | 11/14/25 14:00 | SM 2540 D-20 |

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits