

 ${\tt 284~Sheffield~Street,~Mountainside,~New~Jersey~07092,~Phone:908~789~8900,}\\$ 

Fax: 908 789 8922

## **Duplicate Sample Summary**

Client: Dal Tile - Quartz Plant SDG No.: Q3644

**Project:** Quartz Plant - Stormwater Bench Monitoring **Sample ID:** Q3630-05

Client ID: DSN003DUP Percent Solids for Spike Sample: 0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date	
TSS	mg/L	+/-5	4.00		4.00		1	0		11/14/2025	