

## Report of Analysis

Client: HDR, Inc.  
Project: PVWC Linear Construction  
Client Sample ID: DUPE-0.0-0.5-20251114  
Lab Sample ID: Q3649-03

Date Collected: 11/14/25 12:30  
Date Received: 11/14/25  
SDG No.: Q3649  
Matrix: SOIL  
% Solid: 86.5

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.32		1	0.047	0.28	mg/Kg	11/18/25 08:30	11/18/25 12:17	9012B

Comments: \_\_\_\_\_

U = Not Detected  
LOQ = Limit of Quantitation  
MDL = Method Detection Limit  
LOD = Limit of Detection  
D = Dilution  
Q = indicates LCS control criteria did not meet requirements  
H = Sample Analysis Out Of Hold Time

J = Estimated Value  
B = Analyte Found in Associated Method Blank  
\* = indicates the duplicate analysis is not within control limits.  
E = Indicates the reported value is estimated because of the presence of interference.  
OR = Over Range  
N = Spiked sample recovery not within control limits