

LAB CHRONICLE

OrderID:	Q3649	OrderDate:	11/14/2025 3:02:13 PM
Client:	HDR, Inc.	Project:	PVWC Linear Construction
Contact:	Andrew Wadden	Location:	D41,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3649-01	B5-0.0-0.5-20251114	SOIL			11/14/25 10:30			11/14/25
			Cyanide	9012B		11/18/25	11/18/25 12:10	
Q3649-03	DUPE-0.0-0.5-20251114	SOIL			11/14/25 12:30			11/14/25
			Cyanide	9012B		11/18/25	11/18/25 12:17	
Q3649-06	B4-0.0-0.5-20251114	SOIL			11/14/25 12:25			11/14/25
			Cyanide	9012B		11/18/25	11/18/25 12:17	
			Hexavalent Chromium	7196A		11/17/25	11/17/25 15:14	
			Paint Filter	9095B			11/18/25 10:30	
Q3649-07	B4-0.0-0.5-20251114	SOIL			11/14/25 12:25			11/14/25
			Corrosivity	9045D			11/14/25 16:45	
			Ignitability	1030			11/18/25 09:47	
			Reactive Cyanide	9012B		11/17/25	11/18/25 10:16	
			Reactive Sulfide	9034		11/17/25	11/17/25 13:39	
Q3649-08	B3-0.0-0.5-20251114	SOIL			11/14/25 14:00			11/14/25

LAB CHRONICLE

Cyanide

9012B

11/18/25

11/18/25
12:25