



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: HDR, Inc.

SDG No.: Q3649

Project: PVWC Linear Construction

RunNo.: LB137909

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	7.00	7	100	90-110	11/14/2025
Sample ID: Corrosivity	CCV1	pH	2.01	2.00	101	90-110	11/14/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	11/14/2025

Initial and Continuing Calibration Verification

Client: HDR, Inc.

SDG No.: Q3649

Project: PVWC Linear Construction

RunNo.: LB137917

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.489	0.5	98	90-110	11/17/2025
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.491	0.5	98	90-110	11/17/2025
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.494	0.5	99	90-110	11/17/2025
Sample ID: CCV3 Hexavalent Chromium	mg/L	0.489	0.5	98	90-110	11/17/2025

Initial and Continuing Calibration Verification

Client: HDR, Inc.

SDG No.: Q3649

Project: PVWC Linear Construction

RunNo.: LB137940

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.097	0.099	98	85-115	11/18/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	11/18/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	11/18/2025

Initial and Continuing Calibration Verification

Client: HDR, Inc.

SDG No.: Q3649

Project: PVWC Linear Construction

RunNo.: LB137941

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Cyanide	mg/L	0.097	0.099	98	90-110	11/18/2025
Sample ID: CCV1 Cyanide	mg/L	0.25	0.25	100	90-110	11/18/2025
Sample ID: CCV2 Cyanide	mg/L	0.25	0.25	100	90-110	11/18/2025
Sample ID: CCV3 Cyanide	mg/L	0.26	0.25	104	90-110	11/18/2025