

Report of Analysis

Client: HDR, Inc.
Project: PVWC Linear Construction
Client Sample ID: B3-0.0-1.0-20251117
Lab Sample ID: Q3662-02

Date Collected: 11/17/25 09:30
Date Received: 11/18/25
SDG No.: Q3662
Matrix: SOIL
% Solid: 84.7

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.15	J	1	0.048	0.28	mg/Kg	11/19/25 08:20	11/19/25 10:44	9012B

Comments: _____

U = Not Detected
LOQ = Limit of Quantitation
MDL = Method Detection Limit
LOD = Limit of Detection
D = Dilution
Q = indicates LCS control criteria did not meet requirements
H = Sample Analysis Out Of Hold Time

J = Estimated Value
B = Analyte Found in Associated Method Blank
* = indicates the duplicate analysis is not within control limits.
E = Indicates the reported value is estimated because of the presence of interference.
OR = Over Range
N = Spiked sample recovery not within control limits