



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: HDR, Inc.

SDG No.: Q3662

Project: PVWC Linear Construction

RunNo.: LB137963

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.492	0.5	98	90-110	11/19/2025
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.491	0.5	98	90-110	11/19/2025
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.491	0.5	98	90-110	11/19/2025
Sample ID: CCV3 Hexavalent Chromium	mg/L	0.495	0.5	99	90-110	11/19/2025

Initial and Continuing Calibration Verification

Client: HDR, Inc.

SDG No.: Q3662

Project: PVWC Linear Construction

RunNo.: LB137965

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Cyanide	mg/L	0.095	0.099	96	90-110	11/19/2025
Sample ID: CCV1 Cyanide	mg/L	0.25	0.25	100	90-110	11/19/2025
Sample ID: CCV2 Cyanide	mg/L	0.24	0.25	96	90-110	11/19/2025
Sample ID: CCV3 Cyanide	mg/L	0.25	0.25	100	90-110	11/19/2025

Initial and Continuing Calibration Verification

Client: HDR, Inc.

SDG No.: Q3662

Project: PVWC Linear Construction

RunNo.: LB137975

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	7.00	7	100	90-110	11/20/2025
Sample ID: Corrosivity	CCV1	pH	2.02	2.00	101	90-110	11/20/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	11/20/2025

Initial and Continuing Calibration Verification

Client: HDR, Inc.

SDG No.: Q3662

Project: PVWC Linear Construction

RunNo.: LB137996

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.096	0.099	97	85-115	11/20/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	11/20/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	11/20/2025