

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 11/18/25 12:20

Project: PSEG Camden Gas LPG Replacement Date Received: 11/18/25 Client Sample ID: ARS20-0013 SDG No.: Q3664 Lab Sample ID: Matrix: SOIL Q3664-03

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.19	J	1	0.042	0.25	mg/Kg	11/19/25 08:20	11/19/25 10:59	9012B
Hexavalent Chromium	1.17		1	0.068	0.39	mg/Kg	11/19/25 09:00	11/19/25 13:23	7196A
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		11/19/25 09:07	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits