

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 11/20/25 11:48

Project: Trenton Gas and Appliance Service (TR) Date Received: 11/20/25 Client Sample ID: TR-04-112025 SDG No.: Q3699 Lab Sample ID: Q3699-01 Matrix: SOIL

% Solid: 91.2

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.062	J	1	0.045	0.27	mg/Kg	11/24/25 08:15	11/24/25 11:03	9012B
Hexavalent Chromium	0.076	U	1	0.076	0.43	mg/Kg	11/24/25 08:50	11/24/25 13:17	7196A
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		11/21/25 09:20	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits