

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client:Remington & VernickDate Collected:11/24/25 16:20Project:Saddler PropertyDate Received:11/25/25Client Sample ID:SB-1125-14BSDG No.:Q3719Lab Sample ID:Q3719-08Matrix:SOIL

% Solid: 88.3

Parameter	Conc.	Qua.	DF	MDL	LOQ /	CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Cyanide	0.18	J	1	0.047	0.23	3	mg/Kg	11/26/25 08:15	11/26/25 12:41	9012B	

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits