

LAB CHRONICLE

OrderID:	Q3719	OrderDate:	11/25/2025 11:38:47 AM
Client:	Remington & Vernick	Project:	Saddler Property
Contact:	Justin Zarzecki	Location:	D51

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q3719-01	SB-1125-10A	SOIL			11/24/25 14:40			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:34	
Q3719-02	SB-1125-10B	SOIL			11/24/25 15:00			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:34	
Q3719-03	SB-1125-11A	SOIL			11/24/25 14:05			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:34	
Q3719-04	SB-1125-11B	SOIL			11/24/25 14:15			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:41	
Q3719-05	SB-1125-12A	SOIL			11/24/25 12:20			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:41	
Q3719-06	SB-1125-12B	SOIL			11/24/25 12:30			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:41	
Q3719-07	SB-1125-14A	SOIL			11/24/25 16:15			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:41	

LAB CHRONICLE

Q3719-08	SB-1125-14B	SOIL			11/24/25 16:20			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:41	
Q3719-09	SB-1125-15A	SOIL			11/24/25 15:40			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:49	
Q3719-10	SB-1125-15B	SOIL			11/24/25 15:55			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:49	
Q3719-11	SB-1125-16A	SOIL			11/24/25 13:40			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:49	
Q3719-12	SB-1125-16B	SOIL			11/24/25 13:55			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:49	
Q3719-13	SB-1125-17A	SOIL			11/24/25 15:15			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:49	
Q3719-14	SB-1125-17B	SOIL			11/24/25 15:30			11/25/25
			Cyanide	9012B		11/26/25	11/26/25 12:49	