

CLIENT INFORMATION

REPORT TO BE SENT TO:

COMPANY: Remington + Vernick Engineers
ADDRESS: 2059 Springdale Road
CITY Cherry Hill STATE: NJ ZIP: 08003
ATTENTION: Kyle Carlson e RVE.com
PHONE: 609-682-3049 FAX:

CLIENT PROJECT INFORMATION

PROJECT NAME: Saddler Property
PROJECT NO.: 0400L003 LOCATION: Camden, NJ
PROJECT MANAGER: Kyle Carlson
e-mail: Kyle.Carlson e RVE.com
PHONE: 609-682-3049 FAX:

CLIENT BILLING INFORMATION

BILL TO: API Invoices e RVE.com PO#:
ADDRESS: 2059 Springdale Road
CITY Cherry Hill STATE: NJ ZIP: 08003
ATTENTION: Kyle Carlson PHONE: 609-682-3049

ANALYSIS

DATA TURNAROUND INFORMATION

FAX (RUSH) _____ DAYS*
HARDCOPY (DATA PACKAGE): Standard DAYS*
EOD: _____ DAYS*
*TO BE APPROVED BY CHEMTECH
STANDARD HARDCOPY TURNAROUND TIME IS 10 BUSINESS

DATA DELIVERABLE INFORMATION

☐ Level 1 (Results Only) ☐ Level 4 (QC + Full Raw Data)
☐ Level 2 (Results + QC) ☒ NJ Reduced ☐ US EPA CLP
☐ Level 3 (Results + QC) ☐ NYS ASP A ☐ NYS ASP B
+ Raw Data ☐ Other
✓ EDD FORMAT NJ Haz Site

TAL/TCL+30
VOCs
Cyanide
EPH Cat 2 (hatched)

PRESERVATIVES

COMMENTS

ALLIANCE SAMPLE ID	PROJECT SAMPLE IDENTIFICATION	SAMPLE MATRIX	SAMPLE TYPE		SAMPLE COLLECTION		# OF BOTTLES										COMMENTS
			COMP	GRAB	DATE	TIME		E	F	E	E						
1.	SB-1125-10A	Soil		X	11/24/25	1440	7	3	3	3	1						3 Enclosures = F
2.	SB-1125-10B	Soil		X	11/24/25	1500	7	3	3		1						
3.	SB-1125-11A	Soil		X	11/24/25	1405	7	3	3		1						
4.	SB-1125-11B	Soil		X	11/24/25	1415	7	3	3		1						
5.	SB-1125-12A	Soil		X	11/24/25	1220	7	3	3		1						
6.	SB-1125-12B	Soil		X	11/24/25	1230	7	3	3		1						
7.	SB-1125-14A	Soil		X	11/24/25	1615	7	3	3		1						
8.	SB-1125-14B	Soil		X	11/24/25	1620	7	3	3		1						
9.	SB-1125-15A	Soil		X	11/24/25	1540	7	3	3		1						
10.	SB-1125-15B	Soil		X	11/24/25	1555	7	3	3		1						

SAMPLE CUSTODY MUST BE DOCUMENTED BELOW EACH TIME SAMPLES CHANGE POSSESSION INCLUDING COURIER DELIVERY

RELINQUISHED BY SAMPLER:	DATE/TIME: <u>11/25/2025</u>	RECEIVED BY: <u>[Signature]</u>	Conditions of bottles or coolers at receipt: ☐ COMPLIANT ☐ NON COMPLIANT ☐ COOLER TEMP: <u>3.1</u> °C
1. <u>Mancos Carilli, Jr. RVE</u>		1. <u>[Signature]</u>	Comments: <u>VOCs + Cyanide w/ TAL/TCL+30</u>
RELINQUISHED BY SAMPLER:	DATE/TIME:	RECEIVED BY:	
2.		2.	
RELINQUISHED BY SAMPLER:	DATE/TIME: <u>11-25-25</u>	RECEIVED BY:	
3. <u>[Signature]</u>		3.	

CLIENT INFORMATION

REPORT TO BE SENT TO:
COMPANY: Remington + Vernick Engineers
ADDRESS: 2059 Springdale Road
CITY: Cherry Hill STATE: NJ ZIP: 08003
ATTENTION: Kyle Carlson e RVE.com
PHONE: 609-682-3049 FAX:

CLIENT PROJECT INFORMATION

PROJECT NAME: Saddle Property
PROJECT NO.: 0100L003 LOCATION: Camden, NJ
PROJECT MANAGER: Kyle Carlson
e-mail: Kyle.Carlson@RVE.com
PHONE: 609-682-3049 FAX:

CLIENT BILLING INFORMATION

BILL TO: APInvoices@RVE.com PO#:
ADDRESS: 2059 Springdale Road
CITY: Cherry Hill STATE: NJ ZIP: 08003
ATTENTION: Kyle Carlson PHONE: 609-682-3049

ANALYSIS

DATA TURNAROUND INFORMATION

FAX (RUSH) _____ DAYS*
HARDCOPY (DATA PACKAGE): Standard DAYS*
EDD: _____ DAYS*
*TO BE APPROVED BY CHEMTECH
STANDARD HARDCOPY TURNAROUND TIME IS 10 BUSINESS

DATA DELIVERABLE INFORMATION

☐ Level 1 (Results Only) ☐ Level 4 (QC + Full Raw Data)
☐ Level 2 (Results + QC) ☒ NJ Reduced ☐ US EPA CLP
☐ Level 3 (Results + QC) ☐ NYS ASP A ☐ NYS ASP B
+ Raw Data) ☐ Other
EDD FORMAT: NJ Hazsite

TAL/TCL+30
VOCs
Cyanides
EPH Cat 2 (non Pres.)

PRESERVATIVES

COMMENTS

ALLIANCE SAMPLE ID	PROJECT SAMPLE IDENTIFICATION	SAMPLE MATRIX	SAMPLE TYPE		SAMPLE COLLECTION		# OF BOTTLES										← Specify Preservatives A-HCl D-NaOH B-HNO3 E-ICE C-H2SO4 F-OTHER
			COMP	GRAB	DATE	TIME		E	F	E	E						
1.	SB-1125-16A	Soil		X	11/24/25	1340	7	3	3	1	1						F = Encovers
2.	SB-1125-16B	Soil		X	11/24/25	1355	7	3	3	1	1						
3.	SB-1125-17A	Soil		X	11/24/25	1515	7	3	3	1	1						
4.	SB-1125-17B	Soil		X	11/24/25	1530	7	3	3	1	1						
5.																	
6.																	
7.																	
8.																	
9.																	
10.																	

SAMPLE CUSTODY MUST BE DOCUMENTED BELOW EACH TIME SAMPLES CHANGE POSSESSION INCLUDING COURIER DELIVERY

RELINQUISHED BY SAMPLER:	DATE/TIME:	RECEIVED BY:	Conditions of bottles or coolers at receipt: ☐ COMPLIANT ☐ NON COMPLIANT ☐ COOLER TEMP: 3.1 °C
1. Marco Canale 90 RVE	11/25/2025 9:00	11-25-25	Comments: VOCs + Cyanides w/ TAL/TCL+30
RELINQUISHED BY SAMPLER:	DATE/TIME:	RECEIVED BY:	
2.			
RELINQUISHED BY SAMPLER:	DATE/TIME:	RECEIVED BY:	
3.	11-25-25	3.	