

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 11/25/25 12:12

Project: Mikule Contracting, Inc. (Clifton, NJ) (CL) Date Received: 11/25/25 Client Sample ID: CC-1-112525 SDG No.: Q3723 Lab Sample ID: Q3723-01 Matrix: SOIL

% Solid: 92.1

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
Cyanide	0.13	J	1	0.045	0.27	mg/Kg	11/26/25 08:15	11/26/25 12:56	9012B	
Hexavalent Chromium	0.075	U	1	0.075	0.43	mg/Kg	11/26/25 11:00	11/26/25 14:50	7196A	
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		11/26/25 09:42	9095B	

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits