

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: G Environmental Date Collected: 11/25/25 Project: Buff Date Received: 11/26/25 Client Sample ID: MW3 SDG No.: Q3737 Lab Sample ID: Q3737-01 Matrix: Water Level (low/med): % Solid: 0 low

Cas	Parameter	Conc.	Qua. DI	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-89-6	Iron	7020	1	11.7	50.0	ug/L	12/01/25 11:20	12/01/25 18:42	6010D	M3010A
7439-96-5	Manganese	259	1	2.97	10.0	ug/L	12/01/25 11:20	12/01/25 18:42	6010D	M3010A
7440-23-5	Sodium	221000	1	434	1000	ug/L	12/01/25 11:20	12/01/25 18:42	6010D	M3010A

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits