

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client:G EnvironmentalDate Collected:11/26/25 13:30Project:DiamondDate Received:11/26/25Client Sample ID:GSB2ASDG No.:Q3739Lab Sample ID:Q3739-03Matrix:SOIL

Matrix: SOIL % Solid: 84.7

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Hexavalent Chromium	8.95	1 0.082	0.47	mg/Kg	12/01/25 09:00	12/01/25 13:12	7196A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits