

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client:Remington & VernickDate Collected:11/25/25 12:45Project:Saddler PropertyDate Received:11/26/25Client Sample ID:SB-1125-22SDG No.:Q3742Lab Sample ID:Q3742-09Matrix:SOIL

Matrix: SOIL % Solid: 72.8

Parameter	Conc.	Qua.	DF	MDL	LOQ	/ CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.29	J	1	0.056	0.3	3	mg/Kg	12/03/25 08:05	12/03/25 12:52	9012B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits