

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client:Remington & VernickDate Collected:11/26/25 09:15Project:Saddler PropertyDate Received:11/26/25Client Sample ID:TW-1125-1SDG No.:Q3743Lab Sample ID:Q3743-01Matrix:WATER

% Solid: 0

| Parameter | Conc. Qua. | DF MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|-----------|------------|-----------|------------|-------|----------------|----------------|----------|
| Cyanide | 0.0097 | 1 0.00096 | 0.0050 | mg/L | 12/03/25 10:10 | 12/03/25 13:08 | 9012B |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits