

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** 

Project: Clifton - Metro Electric Division HQ Date Received: 12/03/25 Client Sample ID: 3462 SDG No.: Q3758 Lab Sample ID: Matrix: SOIL Q3758-02

% Solid: 100

Date Collected: 12/03/25 09:25

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.69	Н	1	0	0	pН		12/04/25 08:35	9045D
Flash Point	>212		1	0	0	o F		12/05/25 12:55	1010B
Reactive Cyanide	0.049	U	1	0.0083	0.049	mg/Kg	12/08/25 08:50	12/08/25 11:20	9012B
Reactive Sulfide	4.72	J	1	0.20	10.0	mg/Kg	12/04/25 09:05	12/04/25 12:45	9034

Comments: pH result reported at temperature 22.4 °C, Other method reference for flash point : Pensky-Martens Closed Cup Flash Point ASTM D 9:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits