

Duplicate Sample Summary

Client: Tully Environmental, Inc	SDG No.: Q3760
Project: Transfer Station-SPDES	Sample ID: Q3760-01
Client ID: 001 Willets Pt Blvd (Dec)DUP	Percent Solids for Spike Sample: 0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Ammonia as N	mg/L	+/-20	2.90	OR	2.90	OR	1	0		12/05/2025
Ammonia as N	mg/L	+/-20	2.70	D	2.70	D	2	0		12/05/2025

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	Q3760
Project:	Transfer Station-SPDES	Sample ID:	Q3760-01
Client ID:	001 Willets Pt Blvd (Dec)MSD	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Ammonia as N	mg/L	+/-20	3.90	OR	4.00	OR	1	3		12/05/2025

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	Q3760
Project:	Transfer Station-SPDES	Sample ID:	Q3760-02
Client ID:	002 35th Ave (Dec)DUP	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
TSS	mg/L	+/-5	131		133		1	1.51		12/04/2025

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	Q3760
Project:	Transfer Station-SPDES	Sample ID:	Q3771-02
Client ID:	CompDUP	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
BOD5	mg/L	+/-20	87.4		86.0		1	1.61		12/04/2025

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	Q3760
Project:	Transfer Station-SPDES	Sample ID:	Q3772-01
Client ID:	EFFLUENTMSD	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Oil and Grease	mg/L	+/-18	31.1		30.9		1	0.65		12/08/2025

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	Q3760
Project:	Transfer Station-SPDES	Sample ID:	Q3785-01
Client ID:	WATER-TREATMEN DISCHARGEMSD	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Oil and Grease	mg/L	+/-18	23.8		24.1		1	1.25		12/08/2025

Duplicate Sample Summary

Client:	Tully Environmental, Inc	SDG No.:	Q3760
Project:	Transfer Station-SPDES	Sample ID:	Q3793-01
Client ID:	Q3793-01MSD	Percent Solids for Spike Sample:	0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Oil and Grease	mg/L	+/-18	397		398		1	0.2		12/08/2025