

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Parkway Generation Operating LLC
Project: Linden Generating Station - 402

Client Sample ID: TOWER#1 Lab Sample ID: Q3773-01 Date Collected: 12/03/25 10:40

Date Received: 12/03/25 SDG No.: Q3773 Matrix: WATER

% Solid: 0

Parameter	Conc. Q	Qua. I	OF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
TDS	2040	1	1.00	10.0	mg/L		12/03/25 13:30	SM 2540 C-20
TSS	3.70	J 1	1.00	4.00	mg/L		12/04/25 16:00	SM 2540 D-20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits