

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Parkway Generation Operating LLC
Project: Linden Generating Station - LRSA

Client Sample ID: DSN001 Lab Sample ID: Q3774-03 Date Collected: 12/03/25 09:18

Date Received: 12/03/25 SDG No.: Q3774 Matrix: WATER

% Solid: 0

Parameter	Conc. Qua	ıa. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana. Ana M	Met.
BOD5	34.5	1 0.20	2.00	mg/L		12/04/25 11:25 SM 5	5210 B-16
COD	106	1 1.50	10.0	mg/L		12/05/25 12:48 SM 5	5220 D-11
TSS	9.60	1 1.00	4.00	mg/L		12/04/25 16:00 SM 2	2540 D-20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits