



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q3775

Project: Linden Generating Station - 402

RunNo.: LB138108

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	7.00	7	100	90-110	12/04/2025
Sample ID: Corrosivity	CCV1	pH	2.01	2.00	101	90-110	12/04/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	12/04/2025

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q3775

Project: Linden Generating Station - 402

RunNo.: LB138123

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV						
Flash Point	o F	82.1	81	101	78-84	12/05/2025

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q3775

Project: Linden Generating Station - 402

RunNo.: LB138145

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.097	0.099	98	85-115	12/08/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.24	0.25	96	90-110	12/08/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	12/08/2025

Initial and Continuing Calibration Verification

Client: Parkway Generation Operating LLC

SDG No.: Q3775

Project: Linden Generating Station - 402

RunNo.: LB138145

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
---------	-------	--------	------------	---------------	---------------------------	------------------